Bicycles with SR Suntour Bicycle Forks Recalled by SR Suntour Due to Crash Hazard

http://www.cpsc.gov/en/Recalls/2015/Bicycles-with-SR-Suntour-Bicycle-Forks-Recalled-by-SR-Suntour/

Recall date: June 24, 2015
Product: Bicycles with SR Suntour bicycle forks

Hazard: The bolt that attaches the upper part of the bicycle's fork to the lower part of the fork can break or separate and cause the front wheel to come off the bicycle. This is a crash hazard for riders.

Remedy: Repair
Consumers should immediately stop using bicycles with the recalled SR Suntour bicycle forks and return the bicycle to the place of purchase for a free inspection and repair.

Consumer contact: Call SR Suntour toll-free at 888-820-8458 from 9 a.m. to 4 p.m. Central time Monday through Friday or online at www.srsuntour-cycling.com and click on "Safety Recall Notice" for more information.

Recall Details
Units: About 68,000 in the United States and 33,600 in Canada

Description: This recall involves Cannondale, Diamondback, Giant, GT, INA International, Schwinn, Scott, and Trek brand bicycles with SR Suntour bicycle forks models M3010, M3020, M3030, NEX, and XCT. The recalled forks have serial numbers in the top row beginning with "K" and ending with a number between 141101 and 150127. The fork model and serial numbers are located on the back of the fork's crown. The serial number is the first row. The model number is in the second row. "SR Suntour" is printed on stickers on both sides of the fork legs. A detailed list of the specific model numbers included in the recall is on the firm's website.

Incidents/injuries: There have been 15 reports of the bolts breaking or separating from the bicycles, including two reports of minor injuries such as abrasions, cuts, and bruises.

Sold at: Bicycle stores, sports stores, and mass merchandisers from November 2014 through May 2015 for between $300 and $400 for the bicycles.

Importer/distributor: SR Suntour North America, of Vancouver, Wash. (bicycle forks)

Manufactured in: Kunshan, China